



47. 2nd Floor Suite 261 - View of delaminated fireproofing on top of plaster perimeter ceiling




48. 2nd Floor Suite 261 - Disturbed fireproofing next to hanger wire on corrugated decking above suspended ceiling



49. 2nd Floor Suite 261 - Close-up of fireproofing debris on top of fluorescent light fixture





50. 2nd Floor Suite 261 - Close-up of fireproofing debris on top of fluorescent light fixture



51. 4th Floor vacant center ste - Location of sample #3 - top of fluorescent light fixture



52. 4th Floor vacant center ste - Location of sample #4 - top of fluorescent light fixture